

Supervision of Loading

Service number: DQC - LS - 050018

General

P.O Number 608125
 Product description Aprons
 Item Number OJC001/ OJC002/ OJC010/ OJC011/
 OJC015/ OJC020/ OJC026/ OJC029
 Order quantity 2,061,800
 Supplier XX XXX XX Plastic Co., Ltd
 Loading Location Ningbo, Zhejiang
 Auditors David Wong
 Inspection Date March 8th, 2005

Loading details

Actual Loading List

Item #	Order Quantity (cartons)	Container # CCLU	Container # CCLU
		3042341	2145284
OJC001	3500	1620	1880
OJC002	300	193	107
OJC010	400	302	198
OJC011	400	300	100
OJC015	200	110	90
OJC020	400	198	202
OJC026	100	50	50
OJC029	40	20	20

Container #1

Container number	CCLU 3042341
Container size	20 feet containers
Container color	green
Container sealed number	APL 4308188

Container #2

Container number	CCLU 2145284
Container size	20 feet containers
Container color	green
Container sealed number	AX 837511

Related pictures:





Clean container



Empty container



Appearance of container



Cap of container



Cap of container



Loading



Loading



Loading



Loading



Transporting cartons



Transporting cartons



Full container



Sealed container



Sealed container



Full container



Seal No. of #2 container by Forwarder



Seal No. of #1 container by Forwarder



Method of carton loading



Method of carton loading



Broken carton



Broken carton



Broken carton



Deformed carton



Deformed carton



Deformed carton



Repairing deformed and broken cartons

Major facts and problems found

1. The auditor found 12 export cartons were broken and 28 cartons were deformed, but factory had not spare cartons to replace those defective cartons and container must be delivered to warehouse at once, so factory only repaired those defective cartons.
2. Although the appearance of container was old, but it's safe, no hole was found before loading.
3. The auditor ask the workers to clean the container before loading, the result is satisfactory after the auditor double check the container again.